

NON-COMPLIANCE REPORT # 31787-44


PART NAME: LIMIT SWITCH TRIGGER
PF/SA NO.: PF-391-850-36 R1
WORK ORDER NO.: 31787-44
VENDOR: BT LASER

DATE: 6/11/15
INSPECTOR: K. CABAN
ENGINEER: S. GUILLET EXT.: 4771
PLANNER: D. SHELLEY

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. $\text{⌀} .014 \text{Ⓜ} \text{ A B C}$ OF 2X $\text{⌀} .118$ THRU & $\text{Ⓜ} \text{⌀} .197$ are out of position measuring 0.034"



Engineer Signature: _____

Date: _____