

NON-COMPLIANCE REPORT # 32291-10


PART NAME: STEM
PF/SA NO.: PF-391-738-82 RED
WORK ORDER NO.: 32291-1110
VENDOR ACCEL MFG.

DATE: 9/3/15
INSPECTOR: K. CABAN
ENGINEER: B. ARNOLD EXT.: 8534
PLANNER: DIANNA

Reason for Non-Compliance:

1. R .005 MAX measures 0.0099 (+0.0049" out of tolerance).
2. Inside Diameter $1.00 \pm .020$ measures 1.0525.
 - a. All Surface finish 63 has the finish of stock tube which is greater than 63. (See Photo).

Disposition (UAI, Rework, Scrap, Other):



Engineer Signature: _____

Date: _____