



NON-COMPLIANCE REPORT # 32739-0

PART NAME: SOCKETS, TOOLING BALL
PF/SA NO.: PF-444-316-76
WORK ORDER NO.: 32739-0
VENDOR SWISS SCREW

DATE: 2/26/16
INSPECTOR: K. CABAN
ENGINEER: J. AMANN EXT.: 4768
PLANNER: BILL

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. AUXILIARY MAGNETIC FIELD H, MAGNETIC PERMEABILITY, NOT TO EXCEED 1.05 AT 200 OERSTEDS. - Magnetic permeability measures between 1.060 to 1.179 μ on 2X flat surfaces.

Engineer Signature: _____

Date: _____