

PART NAME:	BASE PLATE	DATE:	6/14/13	
PF/SA NO.:	SA-389-840-21 RED	INSPECTOR:	K. CABAN	
WORK ORDER NO.:	30121-4 (8924593)	ENGINEER:	D. BRUCH	EXT.:
VENDOR	MFD	ROUTE TO:	OV PLATE	
Reason For Non-Compliance:			Action (UA	<u>,RWK,SCRP)</u>
 With respect to the Waterjet cut, holes near end of the length of the plate drifted X= -0.008" & Y= -0.022". (Holes/Threads are within tolerance using hole to hole measurement.) 				
Engineer Signature	:	Dat	e:	