

NON-COMPLIANCE REPORT # 31734-74

PART NAME: SHAFT END BRACKET DATE: 7/1/15

PF/SA NO.: PF-391-738-25 RO INSPECTOR: K. CABAN

WORK ORDER NO.: 31734-74 ENGINEER: JC EXT.: 5109


VENDOR KLY MACH SHOP PLANNER: D. SHELLEY

Reason for Non-Compliance:

1 rejected, 2 accepted

Disposition (UAI, Rework, Scrap, Other):

- 1. $\frac{-.000}{\oplus \emptyset.005 \text{ A B C}}$ of $\frac{\emptyset.126}{-.000}$ THRU is out of true position measuring 0.0094 on SN 104 only.
 - a. 2.864 measured 2.8593
- 2. Φ .005 A B C of .126 +.001 THRU is out of true position measuring 0.0081 on SN 104 only.
 - a. 2.864 measured 2.8600



Engineer Signature:

Date:_____