

NON-COMPLIANCE REPORT # 31787-54


PART NAME: ENCODER SENSOR MOUNT
PF/SA NO.: PF-391-524-98
WORK ORDER NO.: 31787-54
VENDOR: BT LASER

DATE: 5/27/15
INSPECTOR: K. CABAN
ENGINEER: S. GUILLET EXT.: 4771
ROUTE TO: -

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. 2 MASK THREADS AND .073 WIDE SLOTS PRIOR TO ANODIZING , .073 wide slots we not masked, see photo below.
 - a. .073 +.001/-0.000 are within tolerance even with anodizing (.0735)



Engineer Signature: _____

Date: _____