

STANFORD LINEAR ACCELERATOR CENTER HOT WORK PERMIT

Permits issued M-F 08:00 to 15:00 at the SLAC fire station Bldg. 82

Application date/time **2/22/2006 11:22:17 AM**

PERMIT # **00-1402**

BUILDING NO. : **31**

NOTIFY BUILDING MANAGER :

BUILDING MANAGER **D.E. Bostic**

ASSISTANT : **K. Holtemann**

Coordinate this work with the Building Manager (or acting Building manager) before starting any hot work.

Fire detection or suppression equipment requires IMPAIRMENT :

LOCATION : **Inside**

Describe work to be completed : Burning Cutting Soldering
 Brazing Grinding Welding

Permit users are to insure work area is free from combustibles and SLAC Safety and Health standards are adhered to. A fire watch and a fire extinguisher are always required, additional requirements will be included in the work description above. The fire watch is to remain active for an additional 1/2 hour after the completion of the hot work. This permit is valid only if signed by the PAFD and the applicant and shall be available at the work site during the hot work.

Permit Begins : **2/22/2006 07:30**

Permit expires : **2/22/2006 14:30**

PAFD Representative : **Ken Lowell**

Signature : *Ken Lowell*

Applicant : **Karen Holtemann**

Signature : *Karen Holtemann*

Company Represented (Contractor or SLAC) : **SLAC**

SLAC representative (UTR or SLAC supervisor) : **K. Fant**

For Fire or Medical emergencies call 9-911