

# SLAC Process for Lock Out Tag Out (LOTO) of Hazards for Subcontractors

Basic SLAC policy for work performed by a subcontractor is that SLAC will de-energize hazards and apply a SLAC configuration control lock. Subcontractor to use their safety LOTO in addition to SLAC administrative locks prior to starting work.

## No work to be done on energized hazards

