

		Jobs Safety Analysis		Start Date: 10/7/2009 (one year)
JOB/ACTIVITY NAME: Pedestal grinder			JSA # (optional):	
DEPARTMENT/GROUP NAME Metrology / Alignment Engineering Group		BLDG/AREA LOCATION(s): 107		OTHER INFORMATION or REFERENCES::
SCOPE OF WORK Grind Material				

Steps	Potential Hazards	Controls
Check position of tool rest and condition of wheels.	Loose or poorly adjusted tool rests create pinching hazards. Cracked or broken wheels create projectile hazards.	Adjust and tighten tool rests. Confirm wheels are not cracked or broken.
Turn on grinder.	Broken pieces of wheels striking operator	Stand off to the side of the grinder when turning it on.
Grind object.	Abrasion and burns to fingers and hands Flying sparks and debris Pinching hand	Wear leather gloves. Keep fingers and hands away from wheels. Wear safety glasses or face shield. Wear leather gloves. Keep fingers away from pinch points

JOB/ACTIVITY NAME: Pedestal Grinder

START DATE: 10/7/2009

I understand & will adhere to the steps, hazards & controls as described in this JSA. I understand that performing steps out of sequence may pose hazards that have not been evaluated, nor authorized. I will contact my supervisor prior to continuing work, if the scope of work changes or new hazards are introduced.

I understand I have the authority and responsibility to stop work I believe to be unsafe.

Worker Name (please print)

Signature

Date

Brendan Dix

Georg Gassner

Supervisor

Signature

Date

I have communicated area hazards with the supervisor or listed worker(s) for this activity and have coordinated the described activity with affected occupants. The above listed workers are released to perform described scope of work in the following area(s): _____

Mike Racine

Area or Building Manager

Signature

Date