



Job Specific Radiological Work Permit

JSRW/P# Year 2006

Quarter Q 4

Letter Select... Start Date 12/13/2006

Work Area IR 02

Area Manager Zarwell

Extension

1) Scope of Work: IR 02 HLS System to drain 1/2 gallon to lower water level - sample r...

2) Analyze the Hazards:

Radiological Hazards

Specific Item/Area/LCW system	Containment mR/hr	(@30cm mR/hr)	1 meter mR/hr	Contamination levels: dpm/m ³ or pCi/liter for LCW systems
HLS	02	02	02	Historically released

Other Hazards

JHAM	Area Hazards Analysis AHA
JHAM - (JHAM)	

3) Hazard controls to prevent/mitigate hazards:

Radiological Controls

Dosimetry Requirements	Training Requirements

Exposure Controls

Contamination Controls

None

* Full set PPE consist of Coveralls, hood, booties, rubber shoe covers, cotton and rubber gloves

RP Monitoring and Surveys

RP Hold Points

Other Radiological Controls

4) Approvals to perform work within controls

	Print Name	Signature	Date
Responsible or Area Manager			
Radiation Protection	Ann Dill	JD	12/13/2006
ALARA Committee			

Exclusion Category:

Construction Control

Comments/Comments

Engineering Controls

Engineering Controls to mitigate hazards percentage:

100% (check)

With Training Required

100%

Other Engineering Controls

0%

No engineering controls

100% (check)

Workstation Protection
100% (check)

0%

No workstation protection

100% (check)

Personal Protective Equipment

0%

No personal protective equipment

100% (check)

Local Exhaust Ventilation

0%

No local exhaust ventilation

100% (check)

Comments/Comments

With Training Required

100% (check)

Comments/Comments

With Training Required

100% (check)