



## MFD NON-COMPLIANCE REPORT # 30611-13

PART NAME: **NUTBRACKET**  
PF/SA NO.: **PF-381-920-31 R0**  
WORK ORDER NO.: **1442022**  
VENDOR: **MFD**

DATE: **5/21/14**  
INSPECTOR: **K. CABAN**  
ENGINEER: **E. KRAFT** EXT.:  
ROUTE TO: **MTLFNSH**

### Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

Units of measure = mm.



@MMC, bonus tolerance of 0.030mm, the position of the thru slot measures between 0.045mm & 0.073mm (~.002 to .003 inches) out of true position on 3 of the 4 parts.

Engineer Signature: \_\_\_\_\_ Date: \_\_\_\_\_