

NON-COMPLIANCE REPORT # 31732-15



PART NAME: SLIDE SUPPORT ASSY
PF/SA NO.: SA-391-805-51 R5
WORK ORDER NO.: 31732-15
VENDOR BT LASER

DATE: 4/24/15
INSPECTOR: K. CABAN
ENGINEER: JC EXT.: 5109
ROUTE TO:

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. 2X $\varnothing .2501$ measures 0.2488 – 0.2490 on all parts.
 - The standard SLAC Metrology Tooling Ball (0.2498 Diameter) does not fit this undersized diameter.
 - Also, the holes seem to have the black anodized finish, this could cause the undersize diameter



Engineer Signature: _____

Date: _____