



NON-COMPLIANCE REPORT # 31732-44

PART NAME: YAG Crystal Mount
PF/SA NO.: PF-380-520-12 R1
WORK ORDER NO.: 31732-44
VENDOR BT LASER

DATE: 5/18/15
INSPECTOR: K. CABAN
ENGINEER: JC EXT.: 5109
ROUTE TO:

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. $.020 \pm .005$ measures undersized 0.0117 – 0.0125.
2. $\varnothing 1.004 \begin{matrix} +.001 \\ -.000 \end{matrix}$ measures undersized 1.0026 – 1.0028.
3. $1.20 \pm .01$ measures undersized 1.1733 – 1.1740.

Engineer Signature: _____

Date: _____