



## NON-COMPLIANCE REPORT # 31787-27

PART NAME: ALUMINUM SHIELD A  
PF/SA NO.: PF-391-850-60 R0  
WORK ORDER NO.: 31787-27  
VENDOR: BT LASER

DATE: 5/22/15  
INSPECTOR: K. CABAN  
ENGINEER: S. GUILLET EXT.: 4771  
ROUTE TO:

### Reason for Non-Compliance:

### Disposition (UAI, Rework, Scrap, Other):

1.  $1.344^{+0.005}_{-0.002}$  is undersized measuring 1.3371 – 1.3382.
2.  $1.304^{+0.005}_{-0.002}$  is oversized measuring 1.3132 – 1.3142.
3.  $-2X R.020^{+0.000}_{-0.005}$  is undersized measuring 0.0125.

Engineer Signature: \_\_\_\_\_

Date: \_\_\_\_\_