



## NON-COMPLIANCE REPORT # 32291-6

PART NAME: ACTUATOR SPACER  
PF/SA NO.: PF-391-662-95 R0  
WORK ORDER NO.: 32291-6  
VENDOR: MFD

DATE: 8/6/15  
INSPECTOR: K. CABAN  
ENGINEER: B. ARNOLD EXT.: 8534  
PLANNER: DIANNA

### Reason for Non-Compliance:

### Disposition (UAI, Rework, Scrap, Other):

1. Dim #4,  $\boxed{\text{///.003 A}}$  measures 0.0037 (+.0007" out of tolerance).
2. Dim #6,  $\text{Ø}6.378 \pm .005$  measures 6.3659 (-.0072" out of tolerance).
  - a. Roundness of this diameter measures 0.0154"

Engineer Signature: \_\_\_\_\_

Date: \_\_\_\_\_