



NON-COMPLIANCE REPORT # 32875-5

PART NAME: PLT MTG RF SEAL J-SPRING UPBEAM DATE: 4/11/16

PF/SA NO.: PF-444-320-07 INSPECTOR: K. CABAN

WORK ORDER NO.: 32875-5 ENGINEER: B. SCOTT EXT.: 2485

VENDOR: MFD ROUTE TO: B. MISSON

Disposition (UAI, Rework, Scrap, Other):

Reason for Non-Compliance:

1. .005 of Datum -A- measures 0.0068 - 0.0073.
2. .005 A of Thickness .100 measures 0.0071 - 0.0076 out of Parallel to -A-.
3. .002 A of Depth 8X .007 ±.001 measures 0.0069 - 0.0078 out of Parallel to -A-.

Use as is.

B.D. Scott

Engineer Signature: _____ Date: 4/12/16