



NON-COMPLIANCE REPORT # 33073-128

PART NAME: SPACER
PF/SA NO.: PF-380-508-18
WORK ORDER NO.: 33073-128
VENDOR PRO-TEK

DATE: 8/24/16
INSPECTOR: K. CABAN
ENGINEER: B. ARNOLD EXT.: 8534
PLANNER: DIANNA

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. $\varnothing 1.002$ $+0.000/-0.002$ measures 1.0043 (+0.0023" out of tolerance).

Engineer Signature: _____

Date: _____