



## NON-COMPLIANCE REPORT # 33073-130

PART NAME:	SPACER	DATE:	8/25/16		
PF/SA NO.:	PF-380-508-47	INSPECTOR:	K. CABAN		
WORK ORDER NO.:	33073-130	ENGINEER:	B. ARNOLD	EXT.:	8534
VENDOR	PRO-TEK	PLANNER:	DIANNA		

### Reason for Non-Compliance:

### Disposition (UAI, Rework, Scrap, Other):

1.  $\varnothing .792^{+.002}_{-.000}$  measures 0.7913 (-0.0007" out of tolerance).

Engineer Signature: \_\_\_\_\_

Date: \_\_\_\_\_