



**NON-COMPLIANCE REPORT # 33073-84 & -123**


PART NAME: MOD, FLG, DOUBLE-SIDED 6.0  
PF/SA NO.: PF-391-918-06 R0  
WORK ORDER NO.: 33073-84 & -123  
VENDOR: NOR-CAL

DATE: 8/5/16  
INSPECTOR: K. CABAN  
ENGINEER: B. ARNOLD  
PLANNER: D. TIBBETTS  
EXT.: 8534

**Reason for Non-Compliance:**

**Disposition (UAI, Rework, Scrap, Other):**

- 1. 0.450 +.005/-.000 measures 0.4490 - 0.4498 on all 3 parts (-0.0002 to -0.001" out of tolerance)



Engineer Signature: [Signature]

Date: 8-30-16