



NON-COMPLIANCE REPORT # M-24857

PART NAME: PUMPOUT RING
PF/SA NO.: PF-700-931-44 R2
WORK ORDER NO.: M-24857
VENDOR: KLY MACHINE SHOP

DATE: 5/12/15
INSPECTOR: K. CABAN
ENGINEER: HAASE EXT.: 8612
ROUTE TO:

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. $\parallel .002 | A$ measures 0.0041 – 0.0047 on SN 127, 128 & 132 only.
2. $\nearrow .002 | A | B$ of $8X \varnothing 9.690$ measures 0.0025 - 0.0051 on SN 125, 126, 130, 134, 138 & 139 only.
3. $\varnothing 9.000 +0.002/-0.000$ measure undersized: 8.9970 – 8.9987 on all parts

Engineer Signature: _____

Date: _____