




## MFD NON-COMPLIANCE REPORT # 28049-1

PART NAME: **HOMS M2H CHAMBER/MIRROR ASSY, SPARE, FEE**      DATE: **11/23/11**  
PF/SA NO.: **SA-382-103-54**      INSPECTOR: **E. REESE**  
WORK ORDER NO.: **28049-1**      ENGINEER: **D. RICH**      EXT.: **4637**  
VENDOR: **MFD**      ROUTE TO: **VAC ASSY**

### Reason For Non-Compliance:

Action (UAI,RWK,SCRP)

1. Chin Guard exceeds the 0.025mm maximum height above the surface of the mirror. (See Below)



Engineer Signature: \_\_\_\_\_ Date: \_\_\_\_\_