PART NAME: BOTTOM LID DATE: 8/2/12

PF/SA NO.: **PF-235-933-93 R2** INSPECTOR: **K. CABAN**

WORK ORDER NO.: **28877-3** ENGINEER: **B. DUDA** EXT.: **3564**

VENDOR OSV MON-TEK ROUTE TO: MTLFNSH

Reason For Non-Compliance:

Action (UAI,RWK,SCRP)

- 1. All surf. 32 on 2 of 3 parts measure above surface finish 32 ranging from 33.8 58.1.
- 2. Part Number & Revision were not inscribed by vendor.

Engineer Signature:	Date:	