



MFD NON-COMPLIANCE REPORT # 28877-4

PART NAME: **I-ZIP HOUSING, DETECTOR**
PF/SA NO.: **PF-235-934-21**
WORK ORDER NO.: **28877-4**
VENDOR **OSV MON-TEK**

DATE: **8/2/12**
INSPECTOR: **K. CABAN**
ENGINEER: **B. DUDA** EXT.: **3564**
ROUTE TO: **MTLFNSH**

Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

1. All 2 out of 3 parts do not fit mating piece (PF-235-933-93 Bottom Lid). Parts sprung anywhere from 0.015 to 0.027 off of nominal.
 - a. See inspection report for out of tolerance dimensions.
 - b. See actual parts for fit/no fit.
2. Dimension 1.190 ± 0.001 measures 1.1924 – 1.1930.
3. Dimension 1.391 ± 0.001 measures 1.3937 – 1.3941.

Engineer Signature: _____ Date: _____