PART NAME: CLEVIS DATE: 1/23/13

PF/SA NO.: **PF-381-905-51 R0** INSPECTOR: **K. CABAN**

WORK ORDER NO.: 29667-1 (1442022) ENGINEER: T. MONTAGNE EXT.: 8780

VENDOR MFD ROUTE TO: CUSTOMER

Reason For Non-Compliance:

Action (UAI,RWK,SCRP)

1. Surface Finish All Surf $63\sqrt{}$ on all 4 parts have areas where the surfaces do not clean up. See Sample Photo (left).

2. On SN 102 only, 1X of 4X .12 X 45° chamfer has a machining error. See Photo (right).





Engineer Signature:	Date:	
---------------------	-------	--