PART NAME: **CLAMP**

PF-391-851-64 R0

WORK ORDER NO.: 31070-8

VENDOR OSV

PF/SA NO.:

DATE: **6/5/14**


INSPECTOR: M. BENES

ENGINEER: J. DEFEVER EXT.: 8531

ROUTE TO:

Reason For Non-Compliance:

Action (UAI,RWK,SCRP)



1. 0.625 ± 0.005 measures 0.618 (-0.002" out of tolerance).

Engineer Signature: Date: