



Precision Measurement and Inspection

NON-COMPLIANCE REPORT # 32875-5

PART NAME: PLT MTG RF SEAL J-SPRING UPBEAM
PF/SA NO.: PF-444-320-07
WORK ORDER NO.: 32875-5
VENDOR MFD

DATE: 4/11/16
INSPECTOR: K. CABAN
ENGINEER: B. SCOTT EXT.: 2485
ROUTE TO: B. MISSON

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. $\square .005$ of Datum -A- measures 0.0068 – 0.0073.
2. $\parallel .005 A$ of Thickness $.100$ measures 0.0071 - 0.0076 out of Parallel to -A-.
3. $\parallel .002 A$ of Depth $8X .007 \pm .001$ measures 0.0069 - 0.0078 out of Parallel to -A-.

Use as is.

Engineer Signature: *B. Scott*

Date: *4/12/16*