

NON-COMPLIANCE REPORT # 33413-39, 33413-110 & 33415-9


PART NAME: KINEMATIC VEE SUPPORT
 PF/SA NO.: PF-382-909-47 R0
 WORK ORDER NO.: 33413-39, 33413-110 & 33415-9
 VENDOR: GIVMAR

DATE: 12/13/16
 INSPECTOR: K. CABAN
 ENGINEER: C. HARDIN
 PLANNER: DIANNA T.
 EXT.: 2494

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. $\varnothing .0005$ A B C OF $.1260$ (DETAIL B) is out of position on all 12 parts ranging from 0.0036 - 0.0079".
 - a. Y symmetry of $.1260$ measures between -0.0018 to -0.0039 (all on the -Y direction).



Engineer Signature: _____

Date: _____