



NON-COMPLIANCE REPORT # M-24881

PART NAME: CORONA SHIELD
PF/SA NO.: PF-700-914-29
WORK ORDER NO.: M-24881
VENDOR KLY

DATE: 8/11/15
INSPECTOR: K. CABAN
ENGINEER: HAASE EXT.: 8612
PLANNER: SHELLEY

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. $R.190 \pm .005$ measures 0.1833 – 0.1836 on 6 of 7 parts.

Engineer Signature: _____

Date: _____