



MFD NON-COMPLIANCE REPORT #5064

Date: 2/23/04
Job #: 18198
Sub ID: -2/30
Part Number: [PF-444-317-21 Rev. 1](#)
Part Description: Cold Finger, Flange, 5.00" OD
Engineer: A. Ringwall
Ext: 8508

Reason For Non-compliance:

1. $|\oplus|\varnothing.010\textcircled{M}|A|C\textcircled{M}|B|$ of 3X R .31 is out of true position at MMC, 0.0206, 0.0420, 0.0207. See Below:
 - a. Radius 1
 - i. $|2.188| = 2.1962 (-0.0082)$
 - ii. $|0.000| = 0.0063 (+0.0063)$
 - b. Radius 2
 - i. $|.835| = -0.8561 (+0.0211)$
 - ii. $|1.492| = -1.4803 (-0.0117)$
 - c. Radius 3
 - i. $|.835| = -0.8559 (+0.0209)$
 - ii. $|1.492| = -1.4880 (-0.0040)$

All other dimensions are acceptable.

Action Taken:

Engineer Signature: _____ Date: _____