

BL3 Stopper Recheck - shim was installed under 1 leg after alignment.

8-25-03
Perry McDugal

Y Level

$$\begin{array}{r}
 1 \\
 19.932 \\
 - 2.405 \\
 \hline
 22.337 \\
 16. - \\
 \hline
 6.337 \\
 \boxed{6.345} \\
 -0.008
 \end{array}$$

$$\begin{array}{r}
 3 \\
 19.932 \\
 - 2.369 \\
 \hline
 22.301 \\
 16. - \\
 \hline
 6.301 \\
 \boxed{6.302} \\
 -0.001
 \end{array}$$

4	SMIFS	SMISFS
19.932	-42.270	-42.276
- 2.285	57.750	- 57.750
22.217	4.452	4.461
16. -	19.932	19.935
6.217		
6.208		
6.218		
$\boxed{6.221}$	-0.003	

X TC2002

1	2
-7.112	-7.112
$\boxed{-7.114}$	$\boxed{7.104}$
-0.002	+0.008

Z 314.177 -4

$$\begin{array}{r}
 310.177 \\
 \boxed{310.178}
 \end{array}$$

2/8
8/03