

Y Value Scales Centered on Mean Values

Step Between Measured Pole Tips = 10

Dimensions in mm



## LCLS II - SXR Undulator

Nominal Gap = 50

Gap Reading = 50

US Encoder = 50

DS Encoder = 50


27-JUL-2017

S/N = 001

D/S = 01

Run = 25

# Gap Between Pole Tips



Step Between Measured Pole Tips = 10

Dimensions in mm



## LCLS II - SXR Undulator

Nominal Gap = 50

Gap Reading = 50

US Encoder = 50

DS Encoder = 50

27-JUL-2017

S/N = 001

D/S = 01

Run = 25