



Alignment Pin Location After Rough Placement of Plate Over Painted Marks



Alignment Pin Location After Rough Placement of Plate Over Painted Marks

—◆— delta X in.



Alignment Plate Orientation After Rough Placement Over Painted Marks

yaw radians

