

Lessons Learned

Defective Power Strip Causes Safety Concern - Electrical Arc

While lifting a computer's electrical power strip from a desk top at the Savannah River Site, two employees noticed the unit's toggle switch (on/off switch) arc. Fortunately, no one was injured and the defective power strip was removed from service.

- Employees are reminded to visually inspect all electrical equipment and remove from service any equipment that appears defective or damaged.

To access Lessons Learned at SLAC and DOE

Go to SLAC ES&H Website

*http://www-group.slac.stanford.edu/esh/concerns/lessons_learned
links to*

- *SLAC & DOE Lessons Learned Data Base & Mailing List*

<http://www-group.slac.stanford.edu/essg/>