


# May is Electrical Safety Month

## LOCKOUT/TAGOUT (LOTO)



Before you touch any wire of a circuit, you must verify zero voltage using a properly rated tester and use the appropriate level of PPE.

This verification process is considered “Energized Electrical Work Activities” and requires an Approved Electrical Work Plan (EWP).