SLACE NATIONAL ACCELERATOR LABORATORY	Jobs Safety A	Analysis	Start Date: 10/7/2009 (one year)
JOB/ACTIVITY NAME: Saw vertical horizontal		JSA # (optional):	
DEPARTMENT/GROUP NAME Metrology / Alignment Engineering Group	BLDG/AREA LOCATION(s): 107	OTHER INFORMATION or REFERENCES::	
SCOPE OF WORK Cutting material	I		

Steps	Potential Hazards	Controls
Align material on saw platform.	Muscle strain	Position body to maintain balance.
		Maximize use of legs.
		Avoid twisting and overextending.
Operate saw to make cut.	ake cut. Lacerations to hand Keep hands away from saw car	
	metal debris in eyes	Wear safety glasses and/or face shield.

I understand & will adhere to the steps, hazards & controls as described in this JSA. I understand that performing steps out of sequence may pose hazards that have not been evaluated, nor authorized. I will contact my supervisor prior to continuing work, if the scope of work changes or new hazards are introduced.

I understand I have the authority and responsibility to stop work I believe to be unsafe.

Worker Name (please print)	Signature	Date
Brendan Dix		

I have reviewed the steps, hazards & controls described in this JSA with all workers listed above and authorize them to perform the work. Workers are qualified (i.e. licensed or certified, as appropriate, & in full compliance with SLAC training requirements) to perform this activity.

Georg Gassner

Supervisor

Signature

Date

I have communicated area hazards with the supervisor or listed worker(s) for this activity and have coordinated the described activity with affected occupants. The above listed workers are released to perform described scope of work in the following area(s):

Mike Racine

Area or Building Manager

Signature

Date