

## **Jobs Safety Analysis**

S	tart	D	ate

10/7/2009 (one year)

JOB/ACTIVITY NAME:		JSA # (optional):
Band Saw		
DEPARTMENT/GROUP NAME Metrology / Alignment Engineeri Group	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	OTHER INFORMATION or REFERENCES::
SCOPE OF WORK Cutting material		

Steps	Potential Hazards	Controls
Check condition of blade and guard.	Cutting fingers and hands	Avoid contact with blade teeth.
Align materials flat on table.	Pinching fingers or hands	Keep fingers and hands away from pinch points.
Adjust guard to no more than ¼ inch above top of material.	Pinching fingers or hands	Avoid pinch points between guard and housing and between guard and material.
Start blower and saw.	Cutting fingers and hands Injuries from flying sawdust	Keep fingers and hands away from blade. Keep guard in place. Use push bar for smaller materials. Wear safety glasses or face shield.

understand that perform evaluated, nor authorize work changes or new ha	ere to the steps, hazards & cont ning steps out of sequence may ed. I will contact my supervisor azards are introduced.	start Date: 10/7/2009 trols as described in this JSA. I y pose hazards that have not been prior to continuing work, if the scope of stop work I believe to be unsafe.
Worker Name (please print)	<u>Signature</u>	<u>Date</u>
Brendan Dix		
and authorize them to p	erform the work. Workers are o	ed in this JSA with all workers listed above qualified (i.e. licensed or certified, as equirements) to perform this activity.  Date
have coordinated the de	<u>-</u>	r or listed worker(s) for this activity and occupants. The above listed workers are lowing area(s):
Mike Racine		
Area or Building Manager	Signature	Date