

NON-COMPLIANCE REPORT # 33073-116

PART NAME: MODIFIED 3.00 MIRROR
PF/SA NO.: PF-391-834-97 R0
WORK ORDER NO.: 33073-116
VENDOR: LATTICE ELECTRO OPTICS

DATE: 8/8/16
INSPECTOR: K. CABAN
ENGINEER: B. ARNOLD EXT.: 8534
PLANNER: DIANNA

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1. 3. MIRROR SURFACE MUST BE PROTECTED AT ALL TIMES DURING HANDLING AND MACHINING, AND SHALL BE FREE OF NICKS, SCRATCHES.

Upon taking of the protected plastic cover, noticed this surface "rubbing marks" on Mirror Surface on SN 104 only.



Engineer Signature: _____

Date: _____