



Pole Tip Number ----->



Minimum Gap = 7.084

Location of Tooling Ball Center 1 inch above Socket Surface



TB Number	X Corr.	Y Corr.	Z Corr.
#1	-5.07843	0.00499	67.9278
#2	5.07862	0.00816	67.92826
#3	7.08002	0.01382	61.48516
#4	7.07996	0.0077	23.26341
#5	7.08087	0.01014	-23.03481
#6	7.08016	0.00694	-61.37003
#7	5.07492	0.01114	-67.92842
#8	-5.08096	0.00849	-67.92815

Dimensions in Inch