



Pole Tip Number ----->



Minimum Gap = 7.081

Location of Tooling Ball Center 1 inch above Socket Surface



TB Number	X Corr.	Y Corr.	Z Corr.
#1	-5.0786	0.0046	67.92208
#2	5.07867	0.00462	67.92218
#3	7.08003	0.01122	61.47997
#4	7.07901	0.00555	23.25783
#5	7.08014	0.00719	-23.04019
#6	7.07949	0.00165	-61.3759
#7	5.07519	0.00645	-67.93453
#8	-5.08119	0.00552	-67.934

Dimensions in Inch