

Y Value Scales Centered on Mean Values

Step Between Measured Pole Tips = 10

Dimensions in mm



LCLS II - SXR Undulator

Nominal Gap = 12

Gap Reading = 12.00002 US Encoder = 12.00005 DS Encoder = 12


17-JUL-2017

S/N = 001

D/S= 0001

Run= 16

Gap Between Pole Tips



Step Between Measured Pole Tips = 10

Dimensions in mm



LCLS II - SXR Undulator

Nominal Gap = 12

Gap Reading = 12.00002 US Encoder = 12.00005 DS Encoder = 12

17-JUL-2017

S/N = 001

D/S = 0001

Run = 16