



To: Jonathan Dorfan  
CC: Steve Williams  
From: Keith Jobe, NLCTA Safety Officer *W. Williams*  
Tor Raubenheimer, NLCTA Facility Head *1002*  
Subject: NLCTA Pre-Restart Recommendation 5  
Date: 6/7/05

Jonathan,

The Report of the Validation Review of the NLCTA Restart Plan identified 7 Pre-Restart Recommendations to be completed prior to operation of the facility.

This recommendation consists of:

Mitigate bolded items from electrical walk-through spreadsheet.

These items consist of:

Location	Item	Problem
B128 -Control Room	Outlet 2p-128A	Outlet cover not attached, outlet loose.
B062-66	Kicker Pulsed Charge Control	open hole in breaker panel
b062-45	AC cord subject to damage	need to keep cord above door
B062-24-16	Quad power supplies	Lock/secure doors
"Extended Beam Area"	din rail power supply	exposed 110, also need strain relief

I am delighted to inform you that this recommendation has been fully implemented.

Steve Williams requested that the completion of this recommendation be verified by ESO – Perry Anthony.

Name: WAYNE KINDBARGER  
Signature: *Wayne Kindbarger*  
Date: 31 May 2005



To: Jonathan Dorfan  
CC: Steve Williams  
From: Keith Jobe, NLCTA Safety Officer *Keith Jobe*  
Tor Raubenheimer, NLCTA Facility Head *Tor*  
Subject: NLCTA Pre-Restart Recommendation 4  
Date: 6/7/05

Jonathan,

The Report of the Validation Review of the NLCTA Restart Plan identified 7 Pre-Restart Recommendations to be completed prior to operation of the facility.

This recommendation consists of:

Document the configuration of supply power to the tunnel hazards and institute a plan for regular re-verification.

I am delighted to inform you that this recommendation has been fully implemented.

Steve Williams requested that the completion of this recommendation be verified by ESO – Perry Anthony.

Name: WAYNE LINEBARGER  
Signature: *Wayne Linebarger*  
Date: 31 May 2005



To: Jonathan Dorfan  
CC: Steve Williams  
From: Keith Jobe, NLCTA Safety Officer *[Signature]*  
Tor Raubenheimer, NLCTA Facility Head *[Signature]*  
Subject: NLCTA Pre-Restart Recommendation 6  
Date: 6/7/05

Jonathan,

The Report of the Validation Review of the NLCTA Restart Plan identified 7 Pre-Restart Recommendations to be completed prior to operation of the facility.

This recommendation consists of:

Eliminate head bump hazard in E-163 hut.

I am delighted to inform you that this recommendation has been fully implemented.

Steve Williams requested that the completion of this recommendation be verified by Tom Rizzi or Butch Byers.

Name: Thomas V. Rizzi  
Signature: *Thomas V. Rizzi*  
Date: 6/1/05



To: Jonathan Dorfan  
CC: Steve Williams  
From: Keith Jobe, NLCTA Safety Officer *[Signature]*  
Tor Raubenheimer, NLCTA Facility Head *[Signature]*  
Subject: NLCTA Pre-Restart Recommendation 3  
Date: 6/7/05

Jonathan,

The Report of the Validation Review of the NLCTA Restart Plan identified 7 Pre-Restart Recommendations to be completed prior to operation of the facility.

This recommendation consists of:

All RSWCFs will be reviewed. Any RSWCF closed and filed without obtaining all signatures will be examined and the work will be inspected for completion.

I am delighted to inform you that this recommendation has been fully implemented.

Steve Williams requested that the completion of this recommendation be inspected by Sayed Rokni or designate.

Name: SAYED H. ROKNI  
Signature: S. H. Rokni  
Date: 02 JUNE 2005



To: Jonathan Dorfan  
CC: Steve Williams  
From: Keith Jobe, NLCTA Safety Officer *[Signature]*  
Tor Raubenheimer, NLCTA Facility Head *[Signature]*  
Subject: NLCTA Pre-Restart Recommendation 2  
Date: 6/7/05

Jonathan,

The Report of the Validation Review of the NLCTA Restart Plan identified 7 Pre-Restart Recommendations to be completed prior to operation of the facility.

This recommendation consists of:

All procedures listed in the NLCTA BAS need to be reviewed and updated before issuing the BAS

I am delighted to inform you that this recommendation has been fully implemented.

Steve Williams requested that the completion of this recommendation be verified by Sayed Rokni or designate.

Name: SAYED H. ROKNI  
Signature: S. H. Rokni  
Date: 2 JUNE 2005



To: Jonathan Dorfan  
CC: Steve Williams  
From: Keith Jobe, NLCTA Safety Officer *Keith Jobe*  
Tor Raubenheimer, NLCTA Facility Head *Tor Raubenheimer*  
Subject: NLCTA Pre-Restart Recommendation 1  
Date: 6/7/05

Jonathan,

The Report of the Validation Review of the NLCTA Restart Plan identified 7 Pre-Restart Recommendations to be completed prior to operation of the facility.

This recommendation consists of:

All shielding items in the NLCTA, including klystron local shielding items, must be secured and posted as radiation safety items

I am delighted to inform you that this recommendation has been fully implemented.

Steve Williams requested that the completion of this recommendation be verified by Sayed Rokni or designate.

Name: SAYED H. ROKNI  
Signature: S. H. Rokni  
Date: 2 JUNE 2005



To: Jonathan Dorfan  
CC: Steve Williams  
From: Keith Jobe, NLCTA Safety Officer *[Signature]*  
Tor Raubenheimer, NLCTA Facility Head *[Signature]*  
Subject: NLCTA Pre-Restart Recommendation 7  
Date: 6/7/05

Jonathan,

The Report of the Validation Review of the NLCTA Restart Plan identified 7 Pre-Restart Recommendations to be completed prior to operation of the facility.

This recommendation consists of:

Review RF safety in NLCTA with affected staff.

The following operators have been identified as "affected staff" requiring training prior to restart:

- Chris Adolphsen
- Steffan Doebert
- Keith Jobe
- Justin May

I am delighted to inform you that this recommendation has been fully implemented.

Steve Williams requested that the completion of this recommendation be verified by Saul Gold.

Name: SAUL GOLD  
Signature: *[Signature]*  
Date: 6-6-05