



MFD NON-COMPLIANCE REPORT # 27937-49


PART NAME: **ALIGNMENT PIN 1**
PF/SA NO.: **PF-380-545-29**
WORK ORDER NO.: **27937-49**
VENDOR **MFD**

DATE: **7/5/12**
INSPECTOR: **K. CABAN**
ENGINEER: **E. KRAFT** EXT.: **2061**
ROUTE TO: **MTLFNSH**


Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)



1.  is out of profile. The profile is undersized from C-D. View Profile Plot on next page.

Engineer Signature: _____ Date: _____



Notation : ALIGNMENT PIN 1
 Ser. No. : 2
 Element : ACNO

Producer : E. KRAFT
 Part No. :

Draw. No. : PF-380-545-29
 Department: MET. QUALITY IN

		X	Y	Z	Nr.	
Form	0.00620	Min. Deviat.:-0.00633	-0.03713	0.00000	1.39829	9
Lower Toler. :-	-0.00100	Max. Deviat.:-0.00013	-0.18750	0.00000	1.21000	1
Upper Toler. :	0.00100					
Error Magnif.:	3					
No. of points:	18					



2D - CONTOUR

Inspector.:kcaban
 Date:05-JUL-2012
 Time:12:54:04