



MFD NON-COMPLIANCE REPORT # 29464-2


PART NAME: **LENS MOUNT BRACKET**
PF/SA NO.: **PF-391-523-74 R0**
WORK ORDER NO.: **29464-2**
VENDOR: **MFD**

DATE: **11/9/12**
INSPECTOR: **K. CABAN**
ENGINEER: **S. GUILLET** EXT.: **4771**
ROUTE TO: **MTLFNSH**

Reason For Non-Compliance:

Action (UAI,RWK,SCRP)

1. Basic Distance 2X 7.444 measures 7.319 (-0.125"), all holes were machined off the end and not Datum -A- therefore all positions are out of tolerance.



Engineer Signature: _____ Date: _____