



## MFD NON-COMPLIANCE REPORT # 30216-52



PART NAME: **COOLING BRIDGE**  
PF/SA NO.: **PF-391-125-31 R0**  
WORK ORDER NO.: **30216-52**  
VENDOR **OSV (E&S Precision Machining)**

DATE: **7/25/13**  
INSPECTOR: **K. CABAN**  
ENGINEER: **J.C. CASTAGNA** EXT.: **5109**  
ROUTE TO: **MFD EXP**

### Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

1.  $\sqrt{32}$  SURFACES measures 60.0 & 65.0 on both surfaces & on both Parts. Surfaces have scratches (See Images Below for Location/Clarity).



Engineer Signature: \_\_\_\_\_ Date: \_\_\_\_\_