




NON-COMPLIANCE REPORT # 32231-6

PART NAME: YAG SUPPORT RING
PF/SA NO.: PF-380-517-39 R0
WORK ORDER NO.: 32231-6
VENDOR: Ron Witherspoon Inc.

DATE: 9/24/15
INSPECTOR: K. CABAN
ENGINEER: A. CEDILLOS EXT.: 4391
PLANNER: B. MISSON

Reason for Non-Compliance:

Disposition (UAI, Rework, Scrap, Other):

1.  of Datum -A- measures 0.0011 - 0.0017 on 6 out of 7 parts (101,102,103,105,106, & 107).

Engineer Signature: _____

Date: _____