



## MFD NON-COMPLIANCE REPORT # 27937-41

PART NAME: **SWITCH BRACKET**  
PF/SA NO.: **PF-344-606-32**  
WORK ORDER NO.: **27937-41 & 27498-54**  
VENDOR **MFD**

DATE: **6/29/12**  
INSPECTOR: **K. CABAN**  
ENGINEER: **E. KRAFT** EXT.: **2061**  
ROUTE TO: **VAC**

Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

4 PER WORK ORDER (8 TOTAL PARTS)

1. Distance  $0.63 \pm 0.01$  measures 0.648 – 0.650 on 7 of 8 parts. Only one part meets print.

Engineer Signature: \_\_\_\_\_ Date: \_\_\_\_\_