



MFD NON-COMPLIANCE REPORT # 28877-2

PART NAME: **SHIPPING LID**
PF/SA NO.: **PF-235-933-92 R2**
WORK ORDER NO.: **28877-2**
VENDOR **OSV MON-TEK**

DATE: **8/2/12**
INSPECTOR: **K. CABAN**
ENGINEER: **B. DUDA** EXT.: **3564**
ROUTE TO: **MTLFNSH**

Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

1. Dimension 3X 4.600 +0.000/-0.005 measure 4.6018 – 4.6043 (all parts).
2. Dimension 3X 4.100 +0.000/-0.005 measure 4.1002 – 4.1023 (all parts).
3. Part Number & Revision were not inscribed by vendor.

Engineer Signature: _____ Date: _____