



MFD NON-COMPLIANCE REPORT # 29303-2


PART NAME: **BRACKET SUPPORT**
PF/SA NO.: **SA-391-555-96 R0**
WORK ORDER NO.: **29303-2 (893053)**
VENDOR **MFD**

DATE: **10/8/12**
INSPECTOR: **K. CABAN**
ENGINEER: **S. GUILLET** EXT.: **4771**
ROUTE TO: **MTLFNSH**

Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

1. ³² ALL SURF ✓ has some areas on Datum -A- that did not clean up. Surface finish measured ~46-50 in that area (see picture below).



Engineer Signature: _____ Date: _____