




MFD NON-COMPLIANCE REPORT # 29533-1

PART NAME: **FRONT DISK**
PF/SA NO.: **PF-391-653-05 R0**
WORK ORDER NO.: **29533-1**
VENDOR **MFD**

DATE: **11/26/12**
INSPECTOR: **K. CABAN**
ENGINEER: **B. ARNOLD** EXT.: **8534**
ROUTE TO: **MTLFNSH**

Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

1.  of Datum -A- measures 0.0053 – 0.0054 on both parts.
2. $2X \varnothing .064 \begin{matrix} +.001 \\ -.000 \end{matrix} \text{ THRU}$ measures 0.0632 on both parts (-0.0008" undersized).

Engineer Signature: _____ Date: _____