



MFD NON-COMPLIANCE REPORT # 29708-5

PART NAME: **YAG MIRROR MOUNT BLANK**
PF/SA NO.: **PF-380-520-14 R1**
WORK ORDER NO.: **29708-5**
VENDOR **MFD**

DATE: **1/31/13**
INSPECTOR: **K. CABAN**
ENGINEER: **A. CEDILLOS** EXT.: **4391**
ROUTE TO: **LIGHTMS**

Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

- 1) Surface finish of top surface 32 max, measures 38.

Engineer Signature: _____ Date: _____